

TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer / Asst. Executive Engineer)

- 1) Name of School : HILL BLOOMS School,
Pandikkadavu
Mananthavady, Wayanad
- 2) Name of Officer : Geethu mol Kurian, Assistant Engineer,
L. B. O. D. Engrg. Sn. Edavaka O.P.
- 3) Location : Pandikkadavu
- Period for which the Certificate is issued : 2023-24 Academic Year.
- 4) Types of building : Permanent Building
- 5) Nature of defects if any : Nil.

DETAILS OF BUILDING

(a) Foundation and basement	1	6.15x6.15x3.7 Class room 4 nos	Block A GF	
	2	3.00x6.15 Principal		
	(b) Super structure	3		3.00x6.15 Office
		4		8.70x12.50 Kitchen, Dining, Toilet
	5	13.00x2.10 Wash Area		
	6	3.00x6.15 Stair Room		
	7	1.50m Wide Varandah		
(c) Doors and windows	1	6.15x6.15x3.7 Class room 5 nos	Block A FF	
	2	13.2x8.1 Library, Toilet		
	3	3.00x6.15 Stair Room		
	4	1.5m Wide Varandah		
(d) Wood work, wrought and put up	1	6.15x6.15x3.7 Class room 5 nos	Block A SF	
	2	8.70x12.50 Computer Lab		
	3	3.00x6.15 Stair Room		
	4	1.50m Wide Varandah		
(e) Roof	1	9.15x6.15x3.7 Chemistry Lab	Block B GF	
	2	9.15x6.15x3.7 Physics Lab		
	3	6.15x6.15x3.70 Class room 2 nos		
	4	3.00x6.15 Staff Room		
	5	3.00x6.15 Toilet		
	6	3.00x6.15 Electrical Room + Store		
	7	3.00x6.15 Stair Room		
	8	1.50m Wide Varandah		
(e) Roof	1	9.15x6.15x3.7 Biology Lab	Block B FF	
	2	6.15x6.15x3.70 Class room 3 nos		
	3	3.00x6.15 Staff Room		
	4	3.00x6.15 Computer Lab		
	5	3.00x6.15 Stair Room 2 nos		
(e) Roof	1	9.15x6.15x3.7 A V Room	Block B SF	
	2	6.15x6.15x3.70 Class room 4 nos		
	3	3.00x6.15 Stair Room 2 nos		
	4	3.00x6.15 1 Toilet		
	5	1.50m Wide Varandah		
(e) Roof	1	12.90x6.45 GF Office	Block C	
	2	6.15x6.15x3.70 Class Room 2 nos FF		
	3	6.15x6.15x3.70 Class Room 2 nos SF		

Geethu
PRINCIPAL
HILL BLOOMS SCHOOL
P.O. Box. 24, P.O. Mananthavady
Wayanad, Kerala



George
MANAGER
HILL BLOOMS SCHOOL
P.O. Box. 24, Mananthavady P.O.
Wayanad, Kerala

- (f) Flooring :
 (g) Miscellaneous :
 Any major defects noticed which will
 render the building unsafe in any
 7) manner : Nil.
 Whether maintenance works have
 8) been done properly : Yes
 9) Whether the structure is sound for :
 conducting classes : **Yes, Safe at the time of inspection under normal
 wind and weather conditions**

- Notice. 1) The stability of the structure should be examined also with reference to the attitude intensity
 of wind exposure to flood etc.
 2) Any additional observation if deemed necessary for the certificate may be furnished separately
 with the certificate.

*Certified that the school was inspected by me on 14/06/2023 and at the time of inspection, the
 building found to be fit to conduct classes.*

Place : Edavaka G P

Signature.

Date : 14/6/2023

Designation.

[Signature]
 Asst: Engineer
 L S G.D Section,
 Edavaka Grama Panchayat



[Signature]



PRINCIPAL
 HILL BLOOMS SCHOOL
 P.O. Box. 24, P.O. Mananthavady
 Wayanad, Kerala

[Signature]
 MANAGER
 HILL BLOOMS SCHOOL
 P.O. Box. 24, Mananthavady P.O
 Wayanad, Kerala